


Compensation Curve



(Base ambient Temp. 40°C) -10 0 10 20 30 40 50 60

(Base ambient Temp. 45°C) -5 5 15 25 35 45 55

Ambient Temperature °C